

STRUCTURES INSPECTION FIELD REPORT

2-DIST
01

B.I.N.
C42

CULVERT INSPECTION

BR. DEPT. NO.
A-13-043

CITY/TOWN ASHFIELD	8.-STRUCTURE NO. A13043-C42-MUN-BRI	11-Kilo. POINT 000.000	41-STATUS A:OPEN	90-ROUTINE INSP. DATE MAR 21, 2025
07-FACILITY CARRIED HWY PFERSICK RD	MEMORIAL NAME/LOCAL NAME	27-YR BUILT 1987	106-YR REBUILT 0000	YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER SIDS BROOK	26-FUNCTIONAL CLASS Rural Local	DIST. BRIDGE INSPECTION ENGINEER <i>M. P.E. McCabe</i>		
43-STRUCTURE TYPE 319 : Steel Culvert	22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER R. Mancari <i>Reed Mancari</i>	
107-DECK TYPE N : Not applicable	WEATHER Cloudy	TEMP. (air) 1°C	TEAM MEMBERS E. GEMINDER <i>Eli Geminder</i>	

TYPE OF CULVERT:	BARRELS: (In Meters)
SHAPE: PIPE	SIZE: 0.90Wx0.90H NUMBER: 3
MATERIAL: STEEL, CORRUGATED	DEPTH OF COVER (To the nearest tenth of a meter) E: 1.2 W: 1.2
COATING: GALVANIZED	CURB REVEAL (In millimeters) N N

ITEM 62 CULVERT & RETAINING WALLS 7 162 (Dive Report): N 162 (This Report): 7

	Dive This Rpt.	This Rpt.	DEF		Dive This Rpt.	This Rpt.	DEF		Dive This Rpt.	This Rpt.	DEF	
1. Roof	N	N	-	7. Protective Coating	N	6	-	13. Member Alignment	N	7	-	UNDERMINING (Y/N) If YES please explain
2. Floor	N	N	-	8. Embankment	N	7	-	14. Deformation	N	7	-	
3. Walls	N	N	-	9. Wearing Surface	N	7	-	15. Scour	N	7	-	LOAD VIBRATION: Please explain None (X) Minor () Moderate () Severe ()
4. Headwall	N	N	-	10. Railing	N	N	-	16. Settlement	N	7	-	
5. Wingwall	N	N	-	11. Sidewalks	N	N	-	17.	N	N	-	
6. Pipe	N	7	-	12. Utilities	N	N	-	18.	N	N	-	

ITEM 61 CHANNEL & CHANNEL PROTECTION 7

	Dive This Rpt.	This Rpt.	DEF		Dive This Rpt.	This Rpt.	DEF
1. Channel Scour	N	7	-	5. Utilities	N	N	-
2. Embankment Erosion	N	7	-	6. Rip-Rap/Slope Protection	N	N	-
3. Debris	N	7	-	7. Aggradation	N	7	-
4. Vegetation	N	7	-				

STREAM FLOW VELOCITY: Tidal () High () Moderate () Low (X)

ITEM 61 (Dive Report): N

ITEM 61 (This Report): 7

93b-U/W INSP DATE: 00/00/0000

APPROACH CONDITION

	DEF
a. Appr. Pavement Condition	7 -
b. Appr. Roadway Settlement	7 -
c. Appr. Sidewalk Settlement	N -
d.	N -

WEIGHT POSTING

Not Applicable X

Actual Posting: H 3 3S2 Single: N N N N

Recommended Posting: N N N N

Waived Date: 00/00/0000 EJDMT Date: 00/00/0000

Signs In Place (Y=Yes, N=No, NR=Not Required):

At bridge	N	S	Advance	N	S

Legibility/Visibility

ITEM 36 TRAFFIC SAFETY

	36	COND	DEF	ACCESSIBILITY (Y/N/P):	TOTAL HOURS				
A. Bridge Railing	N	N	-	Ladder: N N Other: <table border="1"><tr><td>Needed Used</td><td>Needed Used</td></tr><tr><td></td><td></td></tr></table>	Needed Used	Needed Used			6
Needed Used	Needed Used								
B. Transitions	N	N	-	Boat: N N	PLANS (Y/N): N				
C. Approach Guardrail	N	N	-	Waders: Y Y	(V.C.R.) (Y/N): N				
D. Approach Guardrail Ends	N	N	-		TAPE#:				

RATING

Rating Report (Y/N): N

Date: 00/00/0000

Inspection data at time of existing rating I 62: - Date: 00/00/0000

Recommend for Rating or Rerating (Y/N): N

REASON:

If YES please give priority: HIGH () MEDIUM () LOW ()

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN ASHFIELD	B.I.N. C42	BR. DEPT. NO. A-13-043	8.-STRUCTURE NO. A13043-C42-MUN-BRI	INSPECTION DATE MAR 21, 2025
------------------------------	----------------------	----------------------------------	---	--

REMARKS, PHOTOS & SKETCHES

BRIDGE ORIENTATION

Pfersick Road travels north and south. Sids Brook flows from west and east. This culvert consists of three corrugated steel pipes, each 3' diameter, supporting fill with an asphalt wearing surface. The pipes are numbered from south to north, and report notes are taken from west to east, upstream to downstream, in accordance with the 2015 Bridge Inspection Handbook. **See sketch 1 and photos 1 & 2.**

ITEM 62 - CULVERT

Item 62.6 - Pipe

Portions of the bottoms of all pipes are hidden by sediment.

All pipes, at the west end, have impact damage, 2' long. **See photo 3.**

In pipe 2, at the west end, 1' from the end, there is a separation in the pipe sections, 12" high.

Item 62.7 - Protective Coating

In the bottom half of the pipe, the coating has failed. **See photo 2.**

Item 62.8 - Embankment

The east embankment, over the pipes 1 & 2, has several trees growing, up to 1' diameter.

CONDITION RATING GUIDE

	CODE	CONDITION	DEFECTS
	N	NOT APPLICABLE	Use if structure is not a culvert.
G	9	EXCELLENT	No deficiencies.
G	8	VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.
G	7	GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth symmetrical curvature with superficial corrosion and no pitting.
F	6	SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.
F	5	FAIR	Moderate to major deterioration, or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.
P	4	POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.
P	3	SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.
C	2	CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C	1	"IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.
	0	FAILED	Bridge closed. Replacement necessary.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)

S= Severe/Major Deficiency - (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)

C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extreme hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)

URGENCY OF REPAIR:

I = Immediate- [Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew (if not a State bridge) show up and corrective action is taken.]

A = ASAP- [Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report].

P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].

CITY/TOWN ASHFIELD	B.I.N. C42	BR. DEPT. NO. A-13-043	8.-STRUCTURE NO. A13043-C42-MUN-BRI	INSPECTION DATE MAR 21, 2025
------------------------------	----------------------	----------------------------------	---	--

REMARKS

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.1 - Channel Scour

The upstream channel has minor migration to the north.

At the east outlet, at pipe 3, there is a minor scour hole.

For channel profile readings, refer to **Chart 1**.

Item 61.2 - Embankment Erosion

In the northwest embankment, there is moderate undercutting, up to 24" high x up to 24" deep.

Item 61.3 - Debris

At the west end of the pipes, there is a buildup of debris. **See photo 3.**

Item 61.7 - Aggradation

Refer to Item 62.6 - Pipe.

TRAFFIC SAFETY

Item 36a - Bridge Railing

There are no railings in place over this structure.

Item 36b - Transitions

There are no transitions in place at this structure.

Item 36c - Approach Guardrail

There are no approach guardrails in place at this structure.

Item 36d - Approach Guardrail Ends

There are no approach guardrail ends in place at this structure.

Sketch / Chart / Photo Log

Sketch 1 : Framing Plan.

Chart 1 : Channel profile readings.


Photo 1 : General topside, looking south.

Photo 2 : General underside, looking west, pipe 2 shown.

Photo 3 : West end of the pipes with impact damage and debris buildup.

CITY/TOWN ASHFIELD	B.I.N. C42	BR. DEPT. NO. A-13-043	8.-STRUCTURE NO. A13043-C42-MUN-BRI	INSPECTION DATE MAR 21, 2025
------------------------------	----------------------	----------------------------------	---	--

SKETCHES



Sketch 1: Framing Plan.

CITY/TOWN ASHFIELD	B.I.N. C42	BR. DEPT. NO. A-13-043	8.-STRUCTURE NO. A13043-C42-MUN-BRI	INSPECTION DATE MAR 21, 2025
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS

Photo 1: General topside, looking south.



Photo 2: General underside, looking west, pipe 2 shown.

CITY/TOWN ASHFIELD	B.I.N. C42	BR. DEPT. NO. A-13-043	8.-STRUCTURE NO. A13043-C42-MUN-BRI	INSPECTION DATE MAR 21, 2025
------------------------------	----------------------	----------------------------------	---	--

PHOTOS

Photo 3: West end of the pipes with impact damage and debris buildup.